



## 300 Degree

**Tools**

**Interior**

**Exterior**

**Hard Parts**

**Electronics**

**Distributors**

**Services**

**Contact**

**Home**

Parts and services for the performance driver.

5-25-2010 - Notice to High Performance Fuel Rail purchasers from March 2010 to July 2010 for 300D-012-04 kits. We've had reports of some threading problems for the AN-6 fittings on the ends. If your fittings don't thread almost all the way in like this:



Please [contact us for resolution](#), the fittings are not seating properly and will leak.

Proud sponsor of the [Z-Lab Project](#), [Buckfang Racing](#) & [SPLParts Racing](#)

